

ประกาศชาวเรือ
หมายเลข 2 (ชั่วคราว) /2563
อ่าวไทย, ฝั่งตะวันออก
ชลบุรี, สัตหีบ, เกาะหมุ่ --- ทู่น

- รายละเอียด ---
1. ติดตั้งทุ่นผูกเรือ No 1 (A), FLY.5s, ในตำบลที่ (WGS84 DATUM) แลต. $12^{\circ} 37' 41.88''$ น.,
ลอง. $100^{\circ} 54' 17.64''$ อ.
 2. ติดตั้งทุ่นผูกเรือ No 2 (B), FLY.5s, ในตำบลที่ (WGS84 DATUM) แลต. $12^{\circ} 37' 27.09''$ น.,
ลอง. $100^{\circ} 54' 24.01''$ อ.
 3. ชาวเรือทั้งหลายจงระมัดระวังในการเดินเรือ

แผนที่ซึ่งเกี่ยวข้อง --- 115 A 115 และ 141

ข้อมูลจาก --- กองแผนงานฝ่ายเรือ กรมแผนการช่าง กรมอุทกหารเรือ., ลง 31 มกราคม 2563

ประกาศโดยกรมอุทกศาสตร์
กองทัพเรือ กรุงเทพมหานคร
4 กุมภาพันธ์ 2563

Notice to Mariners
No. 2(T)/20
Gulf of Thailand, East Coast
Chon Buri, Sattahip, Ko Mu --- Buoys

- Details :**
1. Lighted mooring buoy *No 1 (A) Fl.Y.5s*, in the position (WGS84 DATUM)
Lat. $12^{\circ} 37' 41.88''$ N., Long. $100^{\circ} 54' 17.64''$ E. established.
 2. Lighted mooring buoy *No 2 (B) Fl.Y.5s*, in the position (WGS84 DATUM)
Lat. $12^{\circ} 37' 27.09''$ N., Long. $100^{\circ} 54' 24.01''$ E. established.
 3. Mariners are warned accordingly.

Charts affected : 115 A 115 and 141

Source from : Naval Engineering Planning, Naval Dockyard Department., dated 31st January 2020.

Issued by the Hydrographic Department,
Royal Thai Navy, Bangkok, Thailand
4th February 2020