

ประกาศชาวเรือ  
หมายเลข 59/2558 (ชั่วคราว)  
อ่าวไทย  
การสำรวจวัดคลื่นไหวสะเทือน

---

- รายละเอียด --- 1. ประมาณต้นเดือน มิถุนายน 2558 บริษัท ซาลามันเดอร์ เอนเนอร์ยี(บัวหลวง) ลิมิเต็ด จะทำการสำรวจวัดคลื่นไหวสะเทือน แบบ 3 มิติ แปลง B8/38 โดยเรือชื่อ Binhai 517 ภายในพื้นที่ซึ่งล้อมรอบด้วยตำบลที่ตั้งต่อไปนี้ (INDIAN 1975 DATUM) :
- 1.1 แลต.  $10^{\circ} 33'.02$  น., ลอง.  $100^{\circ} 15'.51$  อ.
  - 1.2 แลต.  $10^{\circ} 33'.01$  น., ลอง.  $100^{\circ} 18'.01$  อ.
  - 1.3 แลต.  $10^{\circ} 32'.05$  น., ลอง.  $100^{\circ} 18'.02$  อ.
  - 1.4 แลต.  $10^{\circ} 32'.04$  น., ลอง.  $100^{\circ} 19'.09$  อ.
  - 1.5 แลต.  $10^{\circ} 28'.67$  น., ลอง.  $100^{\circ} 19'.08$  อ.
  - 1.6 แลต.  $10^{\circ} 28'.67$  น., ลอง.  $100^{\circ} 17'.13$  อ.
  - 1.7 แลต.  $10^{\circ} 29'.10$  น., ลอง.  $100^{\circ} 17'.13$  อ.
  - 1.8 แลต.  $10^{\circ} 29'.11$  น., ลอง.  $100^{\circ} 16'.51$  อ.
  - 1.9 แลต.  $10^{\circ} 29'.81$  น., ลอง.  $100^{\circ} 16'.51$  อ.
  - 1.10 แลต.  $10^{\circ} 29'.82$  น., ลอง.  $100^{\circ} 15'.49$  อ.
2. รายละเอียดของเรือ มีดังนี้ :
- |         |   |                                   |
|---------|---|-----------------------------------|
| ชื่อ    | : | Binhai 517                        |
| ชนิด    | : | Vessel and Seismic Specifications |
| สัญชาติ | : | China-Tianjin                     |
3. ชาวเรือทั้งหลายจงระมัดระวังในการเดินเรือ ไม่ควรนำเรือเข้าไปใกล้ ภายในพื้นที่ข้างบน

- แผนที่ซึ่งเกี่ยวข้อง --- 203 และ 045  
ข้อมูลจาก --- กรมเชื้อเพลิงธรรมชาติ, ลง 21 พฤษภาคม 2558

ประกาศโดยกรมอุทกศาสตร์  
กองทัพเรือ กรุงเทพมหานคร  
29 พฤษภาคม 2558

Notice to Mariners  
No. 59/2558 (Temporary)  
Gulf of Thailand  
Seismic Survey

---

**Details :** 1. At the early of June 2015, Salamander Energy (Bualuang) Limited will be conducting 3D seismic survey block B8/38 by the vessel named Binhai 517 within the area enclosed by the following positions (INDIAN1975 DATUM) :

- 1.1 Lat. 10° 33'.02 N., Long. 100° 15'.51 E.
- 1.2 Lat. 10° 33'.01 N., Long. 100° 18'.01 E.
- 1.3 Lat. 10° 32'.05 N., Long. 100° 18'.02 E.
- 1.4 Lat. 10° 32'.04 N., Long. 100° 19'.09 E.
- 1.5 Lat. 10° 28'.67 N., Long. 100° 19'.08 E.
- 1.6 Lat. 10° 28'.67 N., Long. 100° 17'.13 E.
- 1.7 Lat. 10° 29'.10 N., Long. 100° 17'.13 E.
- 1.8 Lat. 10° 29'.11 N., Long. 100° 16'.51 E.
- 1.9 Lat. 10° 29'.81 N., Long. 100° 16'.51 E.
- 1.10 Lat. 10° 29'.82 N., Long. 100° 15'.49 E.

2. Details of the vessels are as follows :

Name	:	Binhai 517
Type	:	Vessel and Seismic Specifications
Flag	:	China-Tianjin

4. Mariners are warned not to approach within above area.

**Chart affected :** 203 and 045

**Source from :** Department of Mineral Fuel, dated 21<sup>st</sup> May 2015

Issued by the Hydrographic Department,  
Royal Thai Navy, Bangkok, Thailand  
29<sup>th</sup> May 2015