

ประกาศชาวเรือ
หมายเลข 174/2556 (ชั่วคราว)
อ่าวไทย, ฝั่งตะวันออก
ชลบุรี, บริเวณทิศเหนือของเกาะสีชัง — ทุ่น

รายละเอียด --- ได้รับรายงานว่า ทุ่นไฟหินกองนอก, Q(9)15s4M, ซึ่งอยู่ในตำบลที่ (INDIAN1975 DATUM)
แลต. $13^{\circ} 11' .47$ น., ลอง. $100^{\circ} 48' .50$ อ. (ใกล้เคียง) ไม่ได้อยู่ในตำบลที่เดิม
ชาวเรือทั้งหลายจงระมัดระวังในการเดินเรือ

แผนที่ซึ่งเกี่ยวข้อง --- 114, 164, 142 และ 001

ข้อมูลจาก --- กองเครื่องหมายทางเรือ, ลง 29 พฤศจิกายน 2556

ประกาศโดยกรมอุทกศาสตร์
กองทัพเรือ กรุงเทพมหานคร
29 พฤศจิกายน 2556

Notice to Mariners
No. 174/2556 (Temporary)
Gulf of Thailand, East Coast
Chon Buri, Ko Si chang Northwards --- Buoy

Details : It has been reported that Hin Kong Nok light - buoy. *Q(9)15s4M*, in the position (INDIAN1975 DATUM) Lat. $13^{\circ} 11' .47$ N., Long. $100^{\circ} 48' .50$ E. (Appr.) is missing from station.

Mariners are warned accordingly.

Charts affected : 114, 164, 142 and 001

Source from : Aids to Navigation Division, dated 29th November 2013

Issued by the Hydrographic Department,
Royal Thai Navy, Bangkok, Thailand
29th November 2013