

ประกาศชาวเรือ  
หมายเลข 21/2558 (ชั่วคราว)  
ฝั่งตะวันตกของประเทศไทย  
ระนอง, เกาะพะยาม --- ไฟ

---

- รายละเอียด --- 1. ไฟเกาะพะยาม, FL.(2)W12s64m10M, ในตำบลที่ (INDIAN DATUM)  
แลต.  $9^{\circ} 43' 45''.55$  น., ลอง.  $98^{\circ} 23' 03''.47$  อ. ไฟดับ  
2. เมื่อมีการแก้ไขไฟแล้ว ไฟจะติดอีกครั้งโดยไม่มีกรออกประกาศชาวเรือเพิ่มเติม  
3. ชาวเรือทั้งหลายจงระมัดระวังในการเดินเรือ

แผนที่ซึ่งเกี่ยวข้อง --- 352, 307, 362, และ 045

ข้อมูลจาก --- สถานีอุทกศาสตร์พังงา, ลง 19 กุมภาพันธ์ 2558

ประกาศโดยกรมอุทกศาสตร์  
กองทัพเรือ กรุงเทพมหานคร  
20 กุมภาพันธ์ 2558

**Notice to Mariners**  
**No. 21/2558 (Temporary)**  
**West Coast of Thailand**  
**Ranong, Ko Phayam --- Light**

---

- Details :**
1. Ko Phayam light, Fl.(2)W12s64m10M, in the position (INDIAN DATUM) Lat.  $9^{\circ} 43' 45''.55$  N., Long.  $98^{\circ} 23' 03''.47$  E. has been extinguished.
  2. Upon completion of repairs, the light will resume its normal function without further notice.
  3. Mariners are warned accordingly.

**Charts affected :** 352, 307, 362, and 045

**Source from :** Phangnga Hydrographic Station, dated 19<sup>th</sup> February 2015

**Issued by the Hydrographic Department,**  
**Royal Thai Navy, Bangkok, Thailand**  
**20<sup>th</sup> February 2015**