

ประกาศชาวเรือ
หมายเลข 62/2558 (ชั่วคราว)
ฝั่งตะวันตกของประเทศไทย
พังงา, เกาะลันตา --- ไฟ

- รายละเอียด --- 1. ไฟเกาะลันตา, FL.(3)20s171m17M, ในตำบลที่ (INDIAN1975 DATUM)
แลต. $8^{\circ} 37' 54''.50$ น., ลอง. $97^{\circ} 39' 06''.50$ อ. ไฟดับ
2. เมื่อมีการแก้ไขไฟแล้ว ไฟจะติดอีกครั้งโดยไม่มี การออกประกาศชาวเรือเพิ่มเติม
3. ชาวเรือทั้งหลายจงระมัดระวังในการเดินเรือ

แผนที่ซึ่งเกี่ยวข้อง --- 307B, 307, 362, และ 045

ข้อมูลจาก --- ร.ล. สายบุรี, ลง 11 มิถุนายน 2558

ประกาศโดยกรมอุทกศาสตร์
กองทัพเรือ กรุงเทพมหานคร
12 มิถุนายน 2558

Notice to Mariners
No. 62/2558 (Temporary)
West Coast of Thailand
Phangnga, Ko Similan --- Light

Details :

1. Ko Similan light, Fl.(3)20s171m17M, in the position (INDIAN1975 DATUM) Lat. $8^{\circ} 37' 54''.50$ N., Long. $97^{\circ} 39' 06''.50$ E. has been extinguished.
2. Upon completion of repairs, the light will resume its normal function without further notice.
3. Mariners are warned accordingly.

Charts affected : 307B, 307, 362, and 045

Source from : HTMS Saiburi, dated 11th June 2015

Issued by the Hydrographic Department,
Royal Thai Navy, Bangkok, Thailand
12th June 2015